




*Fig. 1*




**Fig. 2**




*Fig. 3A*




*Fig. 3B*




*Fig. 4*




*Fig. 5A*




*Fig. 5B*



*Fig. 5C*





*Fig. 6*




**Fig. 7B**

**Fig. 7A**







*Fig. 8A*



*Fig. 8B*




*Fig. 9A*




*Fig. 9B*




*Fig. 10A*




*Fig. 10B*




*Fig. 10C*




*Fig. 11A*





*Fig. 11B*




*Fig. 11C*






*Fig. 13*




- S1: dissolution with vacuum
- S2: casting
- S3: press blooming
- S4: hot rolling
- S5: surface grinding
- S6: cold rough rolling
- S7: soft annealing
- S8: cold finish rolling
- S9: cutting


*Fig. 14A*




*Fig. 14B*



*Fig. 14C*



*Fig. 14D*



*Fig. 15*




Fig. 16A




Fig. 16B




Fig. 16C







Fig. 16D




*Fig. 17A*




*Fig. 17B*



*Fig. 17C*




*Fig. 17D*







*Fig. 18A*




*Fig. 18B*




*Fig. 18C*




*Fig. 18D*




*Fig. 18E*




*Fig. 18F*



*Fig. 18G*



*Fig. 18H*



*Fig. 18I*




Fig. 19

